



Shaking incubator platform

accepts 10-24 screws



configuration of holes in the shaking incubator platform.


Black acrylic base



drilled with $\frac{15}{64}$ " drill bit to give a little play in case my measurements aren't perfect.


$\frac{1}{4}$ " black acrylic

Heat sink pedestals




I'm not going to bother dremeling out the middle section of acrylic for the fan since it'll be in the shaking incubator.

Stand offs



holes circled in green are the ones used to attach it to the incubator platform using 10-24 screws



took off this protective paper later, but left it on when drilling holes